

COMPUTER INTEGRATED MANUFACTURING LABORATORY

LAB CODE: 6ME4-21

FOR III B.TECH- VI SEM –MECHANICAL ENGINEERING



DEPARTMENT OF MECHANICAL ENGINEERING

BHARTIYA INSTITUTE OF ENGINEERING & TECHNOLOGY

NEAR SANWALI CIRCLE, JAIPUR-BIKANER BYE-PASS, NH-11 PO-BAJAJ GRAM SANWALI,
SIKAR, RAJASTHAN 332001

CONTENTS

S. No.	TITLE	PAGE NO.
1	SYLLABUS	3
2	GENERAL INSTRUCTIONS	4
3	LIST OF EXPERIMENTS	5
	• CNC LATHE	6
	• CNC MILLING	23
	• ROBOT PROGRAMMING	37
4	APPENDIX	40

GENERAL INSTRUCTIONS

1. Students should wear the uniform and closed foot wear. Students inappropriately dressed for lab, at the instructor's discretion, are denied access.
2. Eating, drinking and smoking are prohibited in the laboratory at all times.
3. Never work in the laboratory without proper supervision by an instructor.
4. Never carry out unauthorized experiments. Come to the laboratory prepared. If you are unsure about what to do, please ask the instructor.
5. Except the scientific calculator, any other electronic devices are not permitted to use inside the Laboratory.
6. Any damage to any of the equipment/instrument/machine caused due to carelessness, the cost will be fully recovered from the individual (or) group of students.

LIST OF EXPERIMENTS

S. No.	NAME OF THE EXPERIMENT	PAGE No.	DATE OF Exp.	FACULTY SIGNATURE
CNC LATHE OPERATIONS				
1	FACING CYCLE	7		
2	TURNING CYCLE	9		
3	STEP TURNING	11		
4	TAPER TURNING	13		
5	TURNING - CIRCULAR INTERPOLATION	15		
6	THREADING	17		
7	GROOVING	21		
CNC MILLING OPERATIONS				
8	LINEAR AND CIRCULAR INTERPOLATION	24		
9	ENGRAVING	26		
10	MIRRORING	29		
11	ROTATION	31		
12	CIRCULAR POCKETING	33		
13	RECTANGULAR POCKETING	35		
ROBOT PROGRAMING				
14	ROBOT PROGRAMING 1	38		
15	ROBOT PROGRAMING 2	39		

CNC LATHE OPERATIONS

FACING CYCLE

Experiment No:

Date:

AIM : To write a program to obtain the facing cycle in the CNC lathe.

EQUIPMENT REQUIRED: CNC Lathe

PROGRAM :

[BILLET X25 Z70] (Size of the Specimen)

G21 G98;

G28 U0W0;

M06 T1;(Facing Tool)

M03 S1200;

G00 X26 Z0;

G94 X0 Z-0.5 F50;

Z-1.0

Z-1.5

Z-2.0

Z-2.5

Z-3.0

Z-3.5

Z-4.0

Z-4.5

Z-5.0

Z-5.5

Z-6.0


Z-6.5

Z-7.0

Z-7.5

Z-8.0
Z-8.5
Z-9.0
Z-9.5
Z-10.0
G28 U0W0;
M05;
M30;

SKETCH :



RESULT:

TURNING CYCLE

Experiment No:

Date:

AIM: To write a program to obtain the turning cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X28 Z70] (**Size of the Specimen**)

G21 G98;

G28 U0W0;

M06 T1; (**Facing Tool**)

M03 S1000;

G00 X25 Z1;

G90 X24 Z-45 F50;

X23;

X22;

X21;


X20;

G28 U0W0;

M05;

M30;

SKETCH :



TURNING CYCLE

RESULT:

STEP TURNING

Experiment No:

Date:

AIM: To write a program to obtain the step turning cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X28 Z70] (**Size of the Specimen**)

G21 G98;

G28 U0W0;

M06 T1; (**Facing Tool**)

M03 S1000;

G00 X25 Z1;

G90 X24 Z-45 F50;

X23;

X22;

X21;

X20;

X19 Z-40;

X18;

X17;

X16;

X15;

X14 Z-20;

X13;

X12;

X11;


X10;

G28 U0W0;


M05;

M30;

SKETCH:



STEP TURNING CYCLE



RESULT:

TAPER TURNING

Experiment No:

Date:

AIM: To write a program to obtain the taper turning cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X28 Z70] (Size of the Specimen)

G21 G98;

G28 U0W0;

M06 T1; (**Turning Tool**)

M03 S1000;

G00 X25 Z1;

G90 X24 Z-45 F50;


 X20 Z-45 F50;

G28 U0W0;

M05;

M30;

SKETCH:



TAPER TURNING CYCLE

RESULT:

TURNING - CIRCULAR INTERPOLATION**Experiment No:****Date:****AIM:** To write a program to obtain the Circular Interpolation in the CNC lathe.**SOFTWARE REQUIRED:** CNC Lathe Software with FANUC Language.**PROGRAM:**

[BILLET X62 Z70] (Size of the Specimen)

G21 G98;

G28 U0W0;

M06 T1;(Facing Tool)

G00 X13 Z1;

G94 X0 Z-0.5 F50;

Z-1.0;

G71 U0.5 R1;

G71 P10 Q20 U0.1 W0.1 F50;

N10 G01 X05;

G01 Z-1.0;

G01 X15 Z-2;

G01 X15 Z-12;

G03 X20 Z-17 R5;

G01 X20 Z-22;



N20 G02 X25 Z-27 R5;

G28 U0W0;

M05;

M30;

SKETCH:



CIRCULAR INTERPOLATION

RESULT:

DRILLING CYCLE

Experiment No:

Date:

AIM: To write a program to obtain the Drilling Cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X25 Z70] (Size of the Specimen)

G21 G98;

G28 U0W0;

M06 T2;(Center Drill Dia. 3 mm)

M03 S1000;

G00 X0 Z1;

G74 R1;

G74 X0 Z-25 Q500 F30;

G28 U0 W0;

M06 T4; (Drill Dia. 10 mm)

G00 X0 Z1;

G74 R1;

G74 X0 Z-20 Q500 F30;

G28 U0 W0;

M06 T6; (Drill Dia. 12 mm)

G00 X0 Z1;

G74 R1;



G74 X0 Z-10 Q500 F30;

G28 U0W0;

M05;

M30;

SKETCH:



RESULT:

THREADING CYCLE

Experiment No:

Date:

AIM: To write a program to obtain the Threading Cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X25 Z70] (**Size of the Specimen**)

G21 G98;

G28 U0W0;

M06 T1; (**Threading Tool**)

M03 S600;

G00 X26 Z0;


G76 P021560 Q50 R0.1;

G76 X23.774 Z-25 P613 Q100 F1;

G28 U0W0;

M05;

M30;

SKETCH:

RESULT:

GROOVING CYCLE

Experiment No:

Date:

AIM: To write a program to obtain the Grooving Cycle in the CNC lathe.

SOFTWARE REQUIRED: CNC Lathe Software with FANUC Language.

PROGRAM:

[BILLET X25 Z70] (Size of the Specimen)

G21 G98;

G28 U0W0;

M06 T1;(Facing Cycle)

M03 S1000;

G00 X26 Z0;

G94 X0 Z-0.5 F50;

Z-1.0;

Z-1.5;

G28 U0W0;

G00 X26Z0;


G90 X26Z0;

G90 X25 Z-36.5 F30;

X24;

X23;

G28 U0W0;
M06 T3; (**Grooving Tool**)
G00 X24 Z-13.5;
G75 R1;
G75 X70 Z-31.5 P200 Q1000 F30;
G28 U0W0;
M05;
M30;

SKETCH:

RESULT:

CNC MILLING OPERATIONS

LINEAR AND CIRCULAR INTERPOLATION

Experiment No:

Date:

AIM: To write a program to obtain linear and circular interpolation on the given work piece.


SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.

PROGRAM:

```
G21 G94  
G91 G28 Z0  
G28 X0 Y0  
M06 T06  
M03 S1300  
G90 G00 X0 Y0 Z5  
G90 G01 X0 Y0  
X30  
G03 X54 R12  
G01 X82  
G02 X108 R13  
G01 X123  
X80 Y45
```

X40
Y75
G03 X35 Y80 R5
G01 X20
G03 X0 Y80 R10
G01 Y0
M30

SKETCH:



LINEAR AND CIRCULAR INTERPOLATION

RESULT:

ENGRAVING OF LETTERS

Experiment No:

Date:

AIM: To write a program to engrave the letters “SVCET” on the given work piece.

SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.


PROGRAM:

```
G21 G94
G91 G28 Z0
G28 X0 Y0
M06 T06
M03 S1300
G90 G00 X0 Y0 Z5
      [S]
G00 X2 Y30
G01 Z-1 F60
G01 X10 Y30
G03 X15 Y35 R5
G01 X15 Y 37.5
G03 X10 Y42.5 R5
```

G01 X07 Y42.5
G02 X2 Y47.5 R5
G01 X2 Y50
G02 X7 Y55 R5
G01 X15 Y55
G00 Z2
[V]
G00 X20 Y55
G01 Z-1 F60
G01 X27.5 Y30
G01 X33 Y55
G00 Z2
[C]
G00 X51 Y55
G01 Z-1 F60
G01 X43 Y55
G03 X38 Y50 R5
G01 X38 Y35
G03 X43 Y30 R5
G01 X51 Y30
G00 Z2
[E]
G00 X69 Y55
G01 Z-1F60
G01 X56 Y55
G01 X56 Y42.5
G01 X69 Y42.5
G01 X56 Y42.5
G01 X56 Y30
G01 X69 Y30
G00 Z2
[T]
G00 X81.5 Y30

```
G01 Z-1 F60  
G01 X81.5 Y55  
G01 X74 Y55  
G01 X87 Y55  
G00 Z2  
G91 G28 Z0  
G28 X0Y0  
M05  
M30
```

SKETCH:



ENGRAVING OF LETTERS

RESULT:

MIRRORING

Experiment No:

Date:

AIM: To write a program to perform the mirroring operation.


SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.

PROGRAM:

```
G21 G94  
G91 G28 Z0  
G28 X0 Y0  
M06 T06  
M03 S1500  
G90 G00 X0 Y0 Z5  
M98 P4646  
M70  
M98 P4646  
M80  
M70  
M71  
M98 P4646
```

M80
 M81
 M71
 M98 P4646
 M81
 G91 G28 Z0
 G28 X0 Y0
 M05
 M30
 O4646
 G00 X10 Y10
 G01 Z-1.5 F80
 G01 X30 Y10
 G03 X10 Y30 R20
 G01 X10 Y10
 G00 Z5
 M99

SKETCH:



MIRRORING

RESULT:

ROTATION

Experiment No:

Date:

AIM: To write a program to perform the Rotation operation on the given work piece.

SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.

PROGRAM:


```
G21 G94  
G91 G28 Z0  
G28 X0 Y0  
M06 T06  
M03 S1300  
G90 G00 X0Y0 Z5  
M98 P1234  
G68 X0Y0 R90  
M98 P1234  
G68 X0Y0 R180  
M98 P1234  
G68 X0Y0 R270
```

CIM LAB**MECHANICAL / VI SEM**

G69
G68 X0Y0 R360
G69
G91 G28 Z0
G28 X0Y0
M05
M30

O1234
G00 X0Y0
G01 Z-1 F60
G01 X20 Y-10
G01 X40 Y0
G01 X20 Y10
G01 X0 Y0
G00 Z5
M99

SKETCH:



ROTATION

RESULT:

CIRCULAR POCKETING

Experiment No:

Date:


AIM: To write a program to perform the Circular pocketing operation on the given work piece.

SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.

PROGRAM:

```
G21 G94
G91 G28 Z0
G28 X0Y0
M06 T05
M03 S1200
G90 G00X0 Y0 Z5
G170 R0 P0 Q1 X0 Y0 Z-10 I0.5 J0.1 K20
G171 P50 S1500 R60 F60 B1800 J100
G170 R0 P1 Q1 X0 Y0 Z-10 I0 J0 K20
G171 P50 S1500 R60 F60 B1800 J100
G00 Z5
M05
G91 G28 Z0
G28 X0 Y0
M30
```

SKETCH:



CIRCULAR POCKETING

RESULT:

RECTANGULAR POCKETING

Experiment No:

Date:


AIM: To write a program to perform the Rectangular pocketing operation on the given work piece.

SOFTWARE REQUIRED: CNC XMILL Software with FANUC Language.

PROGRAM:

```
G21 G94  
G91 G28 Z0  
G28 X0 Y0  
M06 T04  
M03 S1200  
G90 G00 X0 Y0 Z5  
G172 I30 J30 K0 P0 Q1 R0 X-15 Y-15 Z-10  
G173 I0.1 K0.1 P50 S1500 R60 F50 B1800 J100  
G172 I30 J30 K0 P1 Q1 R0 X-15 Y-15 Z-10  
G173 I0 K0 P50 S1500 R60 F50 B1800 J100  
G00 Z5  
M05  
G91 G28 Z0  
G28 X0 Y0  
M30
```

SKETCH:



RECTANGULAR POCKETING

RESULT:

ROBOT PROGRAMING

ROBOT PROGRAMING 1

Experiment No:

Date:

AIM: To write and execute a robot program to perform a pick and place operation.

SOFTWARE REQUIRED: Pick and place robot integrated with system

PROGRAM:

```
SPEED 80
GRIPPER OPEN
LABEL A
LET A = 0
LABEL MTAB
SPEED 80
JOINT A1= 156.25 A2= 90 A3= 90 A4= 95 A5= 0
JOINT A1= 156.25 A2= 61.79 A3= 119.67 A4= 95 A5= 0
JOINT A1= 156.25 A2= 37.77 A3= 111.6 A4= 153.91 A5= 0
JOINT A1= 156.25 A2= 37.77 A3= 111.6 A4= 153.91 A5= 177.27
GRIPPER CLOSE
JOINT A1= 156.25 A2= 46.65 A3= 110.9 A4= 185.56 A5= 177.27
JOINT A1= 156.25 A2= 68.06 A3= 91.41 A4= 103.9 A5= 177.27
JOINT A1= 0 A2= 90 A3= 90 A4= 95 A5= 0
ADD A = A + 2
IF A < 3 JUMP MTAB
```

RESULTS

ROBOT PROGRAMING 2

Experiment No:

Date:

AIM: To write and execute a robot program to perform a repetitive pick & place operation.

SOFTWARE REQUIRED: Pick and place robot integrated with system

PROGRAM:

```
SPEED 80
GRIPPER OPEN
LABEL A
LET A = 0
LABEL MTAB
SPEED 80
JOINT A1= 156.25 A2= 90 A3= 90 A4= 95 A5= 0
JOINT A1= 156.25 A2= 61.79 A3= 119.67 A4= 95 A5= 0
JOINT A1= 156.25 A2= 37.77 A3= 111.6 A4= 153.91 A5= 0
JOINT A1= 156.25 A2= 37.77 A3= 111.6 A4= 153.91 A5= 177.27
GRIPPER CLOSE
JOINT A1= 156.25 A2= 46.65 A3= 110.9 A4= 185.56 A5= 177.27
JOINT A1= 156.25 A2= 68.06 A3= 91.41 A4= 103.9 A5= 177.27
JOINT A1= 0 A2= 90 A3= 90 A4= 95 A5= 0
ADD A = A + 2
IF A < 3 JUMP MTAB
```

RESULT:

APPENDIX

1. WORD DETAILS

Although the control will, in general, accept part programming words in any sequence, it is recommended that the following word order for each block is used.

N; G; X or U; Z or W; I; K; F; S; T;

O: PROGRAM NUMBER

The “O” followed by a 4 digit numeral value is used to assign a program number.

Example: O1002

N: SEQUENCE NUMBER

The N word may be omitted. When programmed, the sequence number following the N address is a four digit numerical value and is used to identify a complete block of information. Although ascending, descending, or duplicate numbering is allowed, it is best to program in ascending order in increments of 10. This allows for future editing and simplified sequence number search.

G: PREPARATORY COMMAND:

The two digit G command is programmed to set up the control to perform an automatic machine operation. A full list of G codes are given, one G word from each modal group and one non modal G word can be programmed on the same block.

Example:

Valid N 100 G00 G40 G41 G90 G95

*G40 & G41 are from the same group.

A retained G word (Modal) from one group remains active until another G word from the same group is programmed.

One-shot G word (Non-Modal) must be programmed in every block when required.

2. AXIS DEFINITION**Z AXIS**

The Z axis is along a line between the spindle and the tailstock, or the center line of rotation of the spindle. Minus (-) movements of the tool are left toward the head stock; positive (+) movements are right towards the tailstock.

X AXIS

The X axis is 90 degrees from the Z axis (perpendicular to the Z axis). Minus (-) movements of the tool are toward the center-line of rotation, and positive (+) movements are away from the center –line of rotation.

X: X AXIS COMMAND

The X word is programmed as a diameter which is used to command a change in position perpendicular to the spindle center-line.

U: X AXIS COMMAND

The U word is an incremental distance (diameter value) which is used to command a change in position perpendicular to the spindle center-line. The movement is the programmed value.

Z: Z AXIS COMMAND

The Z word is an absolute dimension which is used to command a change in position parallel to the spindle center-line.

W: Z AXIS COMMAND

The W word is an incremental distance which is used to command a change of position parallel to the spindle center-line.

Do not program X & U or Z & W in the same block. If an X axis command calls for no movement it may be omitted.

X, U or P: DWELL

The X word is used with G04 to command a dwell in seconds.

The P word is used with G04 to command a dwell in milliseconds.

I WORD

For arc programming (G02 or G03) , the K Value (with sign) is programmed to define the incremental distance parallel to the Z axis, between the start of the arc and the arc center.

K WORD

For arc programming (G02 or G03), the K value (with sign) is programmed to define the incremental distance parallel to the Z axis, between the start of the arc and the arc center.

The maximum arc for I & K programming is limited to the quadrant. If I or K is zero, it must be omitted.

F WORD

- a) In G99 mode the F word is used to command feed/rev.
- b) In G98 mode the F word is used to command feed/min.
- c) In G32 mode the F word specifies the lead (pitch) of the thread.

P WORD

- a) Used in automatic cycles to define the first block of a contour.
- b) Used with M98 to define a subroutine number.

Q WORD

Q words are used in automatic cycles to define the last block of a contour.

R WORD

For circular interpolation (G02 or G03) the R word defines the arc radius from the center of the tool nose radius (G40 active) - or the actual radius required (G41/ G42 active).

S WORD

- a) In the constant surface speed mode (G96) the four digit S word is used to command the required surface speed in either feet or meters per minute.
- b) In the direct R.P.M mode (G97), the four digit S word is used to command the spindle speeds incrementally, in R.P.M between the ranges available for the machine.
- c) Prior to entering constant surface speed mode (G96) the S word is used to specify a speed constraint, the maximum speed you wish the spindle to run at. To set this restraint the S word is programmed in conjunction with the G50 word.

T WORD

The T words are used in conjunction with "M06". Those are used to call up the required tool on an automatic indexing turret machine, and to activate its tool offsets.

M WORD

An M word is used to initiate auxiliary functions particular to the machine. One M code can be programmed with in one program block together with other part program information.

3. G-CODES LISTING FOR DENFORD FANUC LATHES

G00	Positioning (Rapid Traverse)
G01	Liner Interpolation (Feed)
G02	Circular Interpolation CW
G03	Circular Interpolation CW
G04	Dwell
G10	Offset Value Setting By Program
G20	Inch Data Input
G21	Metric Data Input
G22	Stored Stroke Check On
G23	Stored Stroke Check Off
G27	Reference Point Return Check
G28	Reference Point Return
G29	Return from Reference Point
G30	Return to 2 nd Reference Point
G31	Skip Function
G32	Thread Cutting
G34	Variable Lead Thread Cutting
G36	Automatic Tool Compensation X
G37	Automatic Tool Compensation Z
G40	Tool Nose Radius Compensation cancels
G41	Tool Nose Radius Compensation Left

G42	Tool Nose Radius Compensation Right
G50	Work Co-ord. Change/Max. Spindle Speed setting
G65	Macro call
G66	Macro Modal Call Cancel
G67	Macro Modal Call Cancel
G70	Finishing Cycle
G71	Stock Removal in Turning
G72	Stock Removal in Turning
G73	Pattern Repeating
G74	Peck Drilling in Z Axis
G75	Grooving in X Axis
G76	Thread Cutting Cycle
G90	Cutting Cycle A
G92	Thread Cutting Cycle
G94	Cutting Cycle B
G96	Constant surface Speed Control
G97	Constant Surface Speed Control Cancel
G98	Feed per Minute
G99	Feed per Revolution

Note: - Not All G Codes Apply To Each Machine.

4. M- CODE LIST FOR DENFORD FANUC LATHES

All M Codes marked with an asterisk will be executed at the end of a block (i.e., after the axis movement).

M00	PROGRAM STOP
M01	OPTIONAL STOP
M02	PROGRAM RESET
M03	SPINDLE FORWARD
M04	SPINDLE REVERSE
M05	SPINDLE STOP
M06	AUTO TOOL CHANGE
M07	COOLANT "B" ON
M08	COOLANT "A" ON
M09	COOLANT OFF
M10	CHUCK OPEN
M11	CHUCK CLOSE
M13	SPINDLE FORWARD & COOLANT ON
M14	SPINDLE REVERSE & COOLANT ON
M15	PROGRAM INPUT USING "MIN P" (SPECIAL FUNCTION)
M16	SPECIAL TOOL CALL (TOOL CALL IGNORES TURRET)

M19 SPINDLE ORIENTATE
M20 SPINDLE INDEX A
M21 SPINDLE INDEX 2A
M22 SPINDLE INDEX 3A
M23 SPINDLE INDEX 4A
M25 QUILL EXTEND
M26 QUILL RETRACT
M29 SELECT "DNC" MODE
M30 PROGRAM RESET & REWIND
M31 INCREMENT PARTS COUNTER
M37 DOOR OPEN TO STOP
M38 DOOR OPEN
M39 DOOR CLOSE
M40 PARTS CATCHER EXTEND
M41 PARTS CATCHER RETRACT
M43 SWARF CONVEYOR FORWARD
M44 SWARF CONVEYOR REVERSE
M45 SWARF CONVEYOR STOP
M48 LOCK % FEED AND % SPEED AT 100%
M49 CANCEL M48 (DEFAULT)
M50 WAIT FOR AXIS IN POSITION SIGNAL (CANCELS CONTINUOUS PATH)
M51 CANCEL M50 (DEFAULT)
M52 PULL-OUT IN THREADING = 90 DEGRESS (DEFAULT)
M53 CANCEL M52
M54 DISABLE SPINDLE FLUCTUATION TESTING (DEFAULT)
M56 SELECT INTERNAL CHUCKING (FROM PLC EDITION "F")
M57 SELECT EXTERNAL CHUCKING (FROM PLC EDITION "F")
M62 AUX.1 ON
M63 AUX.2 ON
M64 AUX.1 OFF
M65 AUX.2 OFF
M98 SUB PROGRAM CALL
M99 SUB PROGRAM END